

Technical Note #54

Device Firmware versions for PMCS Supported devices

Subject: Firmware versions for PMCS devices

Applies To: PMCS 5.1, 5.1b, 6.0, 6.5

<i>Devices and Firmware Revision Supported</i>	<i>PMCS 5.1, 5.1b</i>	<i>PMCS 6.0</i>	<i>PMCS 6.0b</i>	<i>PMCS 6.5</i>
POWER LEADER EPM (Comnet & Modbus cards)	Comnet 1.06 Modbus 2.0 - 3.5	Comnet 1.06 Modbus 2.0 - 3.5	Comnet 1.06 Modbus 2.0 - 3.5	Comnet 1.06 Modbus 2.0 - 3.5
POWER LEADER MDP Overcurrent relay (Comnet & Modbus cards)	Comnet 1.0 Modbus 2.0 - 3.5	Comnet 1.0 Modbus 2.0 - 3.5	Comnet 1.0 Modbus 2.0 - 3.5	Comnet 1.0 Modbus 2.0 - 3.5
POWER LEADER Meter	2	2	2	2
EPM 3710 Electronic Power Meter	3011B, 3100B, 4000B	3011B, 3100B, 4000B	3011B, 3100B, 4000B	3011B, 3100B, 4000B
EPM 3720 Electronic Power Meter	B1502	B1502	B1502	B1511
MULTILIN Power Quality Meter (PQM)	2.02	2.02	2.02	3.21
Spectra MicroVersaTrip™	5.16	5.16	5.16	5.16
Enhanced MicroVersaTrip™ C	4.13	4.13	4.13	4.13
Enhanced MicroVersaTrip™ D	4.13	4.13	4.13	4.13
Spectra ECM™ Electronic Control Module	7.2	7.2	7.2	7.2
MULTILIN 239 Motor Protection Relay	2.11	2.11	2.11	2.30
MULTILIN 269 Plus Motor Management Relay	5.2.1	5.2.1	5.2.1	D.6.0.4
MULTILIN SR469 Motor Management Relay	30D243A8.000	30D243A8.000	30D243A8.000	30D261A8.000
MULTILIN SR489 Generator Management Relay	32D120A8.000	32D120A8.000	32D120A8.000	32F131A8.000
MULTILIN 565 Feeder Management Relay	VE2.71	VE2.71	VE2.71	VE2.71
MULTILIN 735 Feeder Relay	25D152D1.000	25D152D1.000	25D152D1.000	25D152D1.000
MULTILIN SR745 Transformer Management Relay	2.1	2.1	2.1	2.40
MULTILIN SR750 Feeder Management Relay	2.1	3.3	3.3	3.60
MULTILIN SR760 Feeder Management Relay	Not supported	3.3	3.3	3.60
POWER LEADER Modbus Concentrator (Main & Segment Processor Firmware)	Main 2.2 Segment 2.12	Main 2.2 Segment 2.12	Main 2.2 Segment 2.12	Main 2.2 Segment 2.12
POWER LEADER Modbus Monitor	1.25 or greater	2.0	2.0	2.0
GE Fanuc Micro 90 PLC	3.01 (20A2)	3.01 (20A2)	3.01 (20A2)	3.01 (20A2)

Programmable Logic Controller (Generic Device)				
ALPS Advanced Line Protection System Comm. Card	Not supported	V0004.00AA15 Comm. 1.67	V0004.00AA15 Comm. 1.67	V0004.00AA15 Comm. 1.67 (check with GERESOLV)
LPS Line Protection System Comm. Card	Not supported	V0004.00AA15 Comm. 1.67	V0004.00AA15 Comm. 1.67	V0004.00AA15 Comm. 1.67 (check with GERESOLV)
DFP100 Digital Feeder Relay	Not supported	4.4	4.4	4.4
DFP200 Digital Feeder Relay	Not supported	2.01	2.01	2.01
EPM 7300	Not supported	1.33 -2.05	1.33 -2.05	1.33 -2.05
EPM 7700	Not supported	Not supported	2.00	2.00
Schweitzer Engineering Laboratories SEL-251 Distribution Relay	Not supported	R406	R406	R406
Schweitzer Engineering Laboratories SEL-321 Phase and Ground Distance Relay, Directional Overcurrent Relay and Fault Locator	Not supported	R500	R500	R500
Schweitzer Engineering Laboratories SEL-351 Directional Overcurrent Relay, Reclosing Relay and Fault Locator	Not supported	R103	R103	R103
Schweitzer Engineering Laboratories SEL-587 Current Differential Relay	Not supported	R503	R503	R503
System Monitor SM-3 Voltage Regulator	Not supported	2.11	2.11	2.11

Keywords:

PMCS, Device, Firmware, Version

Related Notes:

None

Last Revised: 06/18/99 10:42 AM



[Search GE](#) | [GE home page](#) | [GE news](#) | [GE business finder](#) | [GE products & services](#)
[About Us](#) | [What's New](#) | [Products & Services](#) | [Publications](#)
[Process Solutions](#) | [Year 2000](#) | [Contact Us](#)

[Legal Disclaimer](#)